

Work Similar to Gold King **September 1, 2015**

Site Name - Location	Completion Date/Active	Future Work	Type of Work	Situation (Documents)
Colorado				
Golf Tunnel – St. Elmo, CO	Demob 10/30/14 Concrete plug installed Aug 2014		Plug adit – 34 x 12 ft. plug installed along with a 6-in stainless steel pipe pressure relief valve. Discharges 60 to 165 gpm. The AMA states...the potential exists for the natural creation of a dam from internal mine structure collapse and along with ice dams formed over the winter could back up contaminated water and result in a catastrophic blowout....”	AMA 7/30/13 Polrep 10/29/14 EE/CA 6/13/12
Pennsylvania Mine – Montezuma, CO	2014-ongoing 1 st bulkhead in place	Dewatering Level F & C reclaim 634,000 ft ³ waste piles Possible second bulkhead in 2015, possible construction of a passive water treatment system 2016.	Plug 2 adits – underground bulkheads, sequenced in phases over years, collapsed adit, water diverted, ACD discharged into treatment ponds Discharge from the adit reached during peak flow (Aug 3 and 8) 3,800 gpm.	AM 6/9/13 Polrep 8 (pvt) 7/11/15 TDD end dt 10/31/13 SOW 6/19/2013
Red & Bonita – Silverton, CO	Active - ongoing		Removed mine waste from settling ponds, piping, improved drainage, preparing to install bulkhead, provide hydraulic control and manage. Drains at about 300 gpm, removing precipitated solids from mine adit, preparing mine adit for bulkhead	Polrep #1 12/1/14 Removal Site Evaluation 3/30/13 Bulkhead Design Plan PP March 2015
Standard Mine – Crested Butte, CO	Active		Main tunnel collapses, 80-ft from opening, plans are to install a flow-through bulkhead. Water being	Final progress report 08/19/13

			diverted into treatment area blockage cleared in preparation of bulkhead, rehab adit.	
Terrible (Isle) Mine – Westcliffe, CO	5/30/2012		Mine site, waste rock and tailings, snow and runoff events, cause AMD to pour into Oak Creek	Final Polrep 2 6/16/14 AMA 7/23/12
Summitville Mine, Whitman Fork – Del Norte, CO	7/11/13		Heavy runoff could strip the riprap in the rundown structure channel and erode soil. Culvert headwall could be compromised. If headwall collapses, could threaten the integrity of the Summitville Dam Impoundment.	Final Polrep 7/31/13 AMA 12/4/13
Burleigh Tunnel – Silver Plume, CO	11/15/11		Storm events cause excessive AMD drainage from the Tunnel onto Main Street. Pipes were installed to assist in drainage and to contain and maintain drainage.	AM 11/3/2011 Polrep #1 8/17/12
Carribeau Mine – Ophir, CO	Assessment		Consists of a collapsed mine adit, waste-rock dump, remnants of a mill and tailings deposits. The adit flows into Howard Fork. Recent settlement with RP to fund removal action.	Assessment 9/1/10
Leadville Mine Drainage Tunnel – Leadville, CO	2/19/2008 8/30/14		Collapsed tunnel has caused water to back up....as much as 1 billion gallons contaminated with metals. Drainage pipe was installed, bedded and backfilled. OU6 Stray Horse Gulch retention ponds (Mikado Pond) high run-off threatened to overtop pond, debris removal, dewatering, excavator and skid to remove sediments-as much as 15 truck load of sediments removed.	Polrep #11 Initial/Final Polrep #1
James Creek – Boulder, CO	107/2011		Private citizen clearing the adit of a purchased mine, dug too close releasing 15,000 to 30,000 gallons of a mixture of water, dirt, mine tailings and waste rock, traveled 200 ft and then emptied into James Creek	Initial/Final Polrep 10/7/2011
Central City/Clear Creek OU3 Virginia Canyon, Clear Creek County, CO		05/15/06	Two Brothers Mine and Virginia Canyon-- heavy precipitation events have resulted in acid mine drainage to Clear Creek and its tributaries. There are some 205 mine waste piles in the area with runoff/migration. According to a 2001 Reclamation Feasibility Report-Virginia Canyon...the acidity of	Initial/Final Polrep dated 5/15/06

			the mine waste and toxicity of the metals is high enough to create health/environmental concerns.	
Captain Jack Mill NPL Site, Ward, CO	5/14/2007		The Big 5 Area contains an adit, 2 dumps, a mill and settling pond. AMD stream flows several gal/minute from the adit tunnel. It appears in at least two areas that the tunnel has collapsed and prior to mitigation of the mine adit drainage via plugging of the seep and other drainage openings, a reconnaissance of tunnel/collapsed areas must be accomplished. It is likely that a collapse will fail and a sudden uncontrolled release of AMD will be released into Left Hand Creek.	Final Polrep #3 5/14/2007
French Gulch, Breckenridge, CO	2009		The abandoned Wellington Oro silver/zinc mine , with more than 12 miles of tunnel, was active at the turn of the last century. AMD from the mine used to seep to French Creek where elevated zinc concentrations were primarily responsible for the absence of fish in French and Blue creeks. A water treatment plant to extract zinc and cadmium was built in 2008 near the Wellington-Oro mine. Water discharges no longer pose a risk to the environment. USFS conducted cleanups on 2 mine sites on their lands.	Action Memorandum 2002
Bonanza Mining, west of Villa Grove, CO	1994		ASARCO began conducting cleanup in 1994 which included the consolidation of mine wastes and in 1999 the plugging of the Rawley 12 Adit.	
Idarado Natural Resource Damage Site, Telluride, CO	1992		As a result of a settlement 11 tailing piles were cleaned, sediments cleared from the underground mine, surface runoff around mine wastes were diverted and internal mine waters diverted away from highly mineralized regions.	
Remainder of Region 8				
Bullion Mine OU6 – Jefferson County, Montana	10/29/14		A relief well was installed to prevent a potential blowout of 2.5 M g of AMD. Water had accumulated behind a debris plug, water treated, drainage system	AM 6/19/14 Progress Report 11/4/14

			installed. (connected with below Crystal Mine)	
Crystal Mine OU5 Basin Mining Area Basin, Montana	9/15/14		1,000 yds ³ contaminated sediment removed, relief well installed near Bullion Mine Adit, treatment of 2.5 M g., water treated, drainage system installed (connected with above Bullion Mine)	AM 7/30/2014 Progress Report 11/4/14
Basin Mining Area – near Basin MT	09/30/2007		The Buckeye/Enterprise Mines, located immediately adjacent, have 25,000 cubic yards of metals and an ARD generating tailings pile/pond of 15,000 cubic feet. Impacts to Basin and Cataract Creek are of concern. The Morning Mine contains 2,400 cubic yards of mine waste that contain heavy metals exceeding threshold levels for water and aquatic standards	Final Polrep #4 12/11/08
Other Regions				
R10 Jack Waite Mine –Coeur D Alene, ID	10/24/12		Pooling of water, highly contaminated, adits, rock piles, tailing impoundments, discarded debris	Polrep 7 10/30/12 AM 7/31/12
R10 Formosa Mine Emergency Response, Silver Butte, Oregon	3/27/2009		Upon mine closure, adits were capped with concrete and limestone and a drainage pipe and water dispersal field were installed. The drain fields failed in the 90s but the adits were directed downslope where bedrock has acid neutralization characteristics.	Polrep #1
Cleveland Mine and Mill Site, Hunters, WA	5/8/2007		A silver-lead mine complex within the Hunters Creek watershed. A removal action to mitigate the potential for a reoccurrence of a sudden, substantial and uncontrolled release of subsurface water from the mine and to minimize the effects. Mine waste removal, earthen berm	No documents on web site.
R9 Argonaut Mine Tailings – Jackson, CA	Active		Site has 6 areas, ore storage, cyanide plant, earthen tailings dam, Grey Sands tailings, Lower earthen surface water drainage area. The dam is structurally unsafe, 400 yards from downtown Jackson, The impoundment is filled with sediment and water cascades over the top during storms. A report is due in January 2016.	Fact Sheet 8/10/15 SI 7/29/15

R9 Sheldon Mine – Walker, AZ	Jun 2013		Surface drainage systems that diverted waters are choked with sediment, high levels of lead and arsenic. Orange colored liquid emanates from toe.	AM 1/31/13
---------------------------------	----------	--	---	------------